



Hyper Silver

Coating

HSK100

Product Description

Dupli-Color® Hyper Silver Coating is a two can system that creates a deep silver metallic finish over all types of wheel finishes. The system includes the Hyper Silver base coat. The Clear top coat adds gloss, depth, and protection from the elements. It is resistant to brake dust, road abrasion, chipping, and fading. These characteristics make it ideal for customizing any car, bike, truck wheel, or accessory.

Product Characteristics

Color: Hyper Silver (Base Coat)

Finish: Metallic

Properties

Product Weight: 6.32 lb/gal (Base)
6.30 lb/gal (Clear)

Flash Point: Propellant < 0° F

Preferred Application

Dupli-Color Hyper Silver Coating provides optimum performance when this application method is followed.

Prep	CM541	Grease & Wax Remover
Coat	HSK100	Hyper Silver (Base Coat)
Clear	HSK100	Hyper Silver (Clear Coat)

Refer to application box for more specific instructions

Uses

Wheels, Trim, & Accessories.

Surfaces:

Metal & Aluminum.

Packaging

Fill Weight: Two 11 oz cans

Per Case: 2 kits

Case Weight: 4 lbs

Cases/Pallet: 192

Units/Pallet: 384 cans

Application

For maximum product performance read the entire label and directions prior to paint application.

Base Coat:

Prepare surface by removing dirt, wax, and grease using a quality Grease & Wax Remover. Scuff sand the surface with a Scotch Brite pad for maximum adhesion. High quality polished metal will give the best end results.

Mask-off surrounding areas to protect from overspray. Use at temperatures between 60° F (16° C) and 95° F (35° C), and when humidity is less than 70%. Do not apply in direct sun.

Shake can vigorously for one full minute after mixing ball moves freely. After each minute of use, shake the can for an additional 10 seconds. To spray, hold the can parallel 8-10 inches from the surface to be painted and use in an even, sweeping motion. Apply 2-3 coats of Hyper Silver Base Coat in light even coats until desired color and coverage is achieved. Allow 10 minutes between coats. Dries to the touch in 30 minutes. Can be handled in one hour. Covers approximately 12-14 square feet.

Once Hyper Silver Base Coats are complete, let the surface dry for one hour. Topcoat using Dupli-Color Hyper Silver Clear Coat. Apply Clear Coat according to application instructions on the clear coat can.

Clear Coat:

Apply Hyper Silver Base Coat following the directions on the can and allow 1 hour to dry, before applying Hyper Silver Clear Coat.

Shake can vigorously for one full minute after mixing ball moves freely. After each minute of use, shake the can for an additional 10 seconds. Use at temperatures between 60° F (16° C) and 95° F (35° C), and when humidity is less than 70%. Do not apply in direct sun.

To spray, hold the can parallel 8-10 inches from the surface to be painted and use in an even, sweeping motion. Apply Hyper Silver Clear Coat in 2-3 light coats allowing 10 minutes between coats. Apply 1-2 heavier wet coats allowing 20 minutes between each coat. Dries to the touch in one hour. Covers approximately 12-14 square feet.

Once Dupli-Color Hyper Silver Coating System is complete, allow 4-5 hours dry time before substrates are reinstalled or put to use.

(V.1, 12/12)